

DAFTAR TABEL

2.1	Spesifikasi Flex Sensor	12
2.2	Nama Pin LCD Karakter dan Fungsi	18
3.1	Tabel Penjelasan Definisi Operasional	29
3.2	Jadwal Kegiatan	33
4.1	Data Hasil Pengukuran Test Point Mode Overbite	35
4.2	Data Hasil Pengukuran Test Point Mode Overjet	36
4.3	Data Hasil Output Sensor	38
4.4	Data Hasil Perbandingan Pengukuran Mode Overbite	38
4.5	Data Hasil Perbandingan Pengukuran Mode Overjet	40
4.6	Data Statistik Mode Overbite	41
4.7	Data Statistik Mode Overjet	41