

ABSTRAK

Kementerian Kesehatan RI
Politeknik Kesehatan Kemenkes Surabaya
Jurusan Kesehatan Lingkungan
Program Studi Sanitasi Program Diploma Tiga Kampus Magetan
Karya Tulis Ilmiah, Juni 2024

Mohammad Aqiilah Fahmi

“Kondisi Sanitasi Masjid Agung Baitussalam Kabupaten Magetan Tahun 2024”

Xv Halaman + 62 Halaman isi + 5 Tabel + 18 Gambar + 4 Lampiran

Berdasarkan Kep. Menkes 288/Menkes/SK/III/2003 Tentang Pedoman Penyehatan Sarana dan Bangunan. Masjid Agung Baitussalam Kabupaten Magetan di bagian lantai tempat wudhu putra terlihat kotor dan terdapat genangan air yang bisa menyebabkan kepeleset/kecelakaan pada pengunjung/jama'ah serta dinding Masjid Bagian luar Masjid yang retak-retak, warna cat yang sudah pudar dan kotor. Artinya Masjid Agung Baitussalam Kabupaten Magetan beberapa bangunan/fasilitas masjid kurang perawatan/terpelihara dengan baik.

Penelitian deskriptif menggunakan 3 variabel yaitu Bangunan Luar, Bangunan Bagian Dalam, dan Fasilitas Sanitasi. Penelitian ini bertujuan untuk menilai Kondisi Sanitasi Masjid Agung Baitussalam Kabupaten Magetan dengan pengambilan data menilai Kondisi Sanitasi Masjid yaitu Alat dan bahan menggunakan Koesioner dan alat tulis, Observasi dilakukan untuk mengetahui Kondisi Sanitasi Masjid dengan koesioner, Wawancara dilakukan untuk mendapatkan informasi dan bahan penelitian dengan menggunakan kuesioner, Dokumentasi menggunakan kamera dokumentasi, Pengukuran fisik menggunakan alat Higrometer yaitu kelembaban, alat Termometer yaitu ventilasi/suhu, alat pH Meter yaitu Air fisik.

Hasil penelitian Kondisi Bangunan Bagian Luar di Masjid Agung Baitussalam Kabupaten Magetan adalah 76 poin Memenuhi syarat, Bangunan Bagian Dalam di Masjid Agung Baitussalam Kabupaten Magetan adalah 462 poin Memenuhi Syarat, Fasilitas Sanitasi di Masjid Baitussalam Kabupaten Magetan adalah 400 poin Memenuhi Syarat, Kondisi Sanitasi di Masjid adalah 938 poin Memenuhi Syarat dan dilakukan pengukuran fisik Kelembaban 60%, Suhu 27°C, Air fisik (rasa, bau, dan warna).

Kata Kunci : Sanitasi Masjid, Masjid Agung Baitussalam, Kab. Magetan

ABSTRACT

Indonesian Ministry of Health
Ministry of Health Surabaya Health Polytechnic
Department of Environmental Health
Sanitation Study Program Diploma Program Three Magetan Campuses
Scientific Writing, June 2024

Mohammad Aqiilah Fahmi

“Sanitary Conditions Of The Baitussalam Great Mosque, Magetan District”

Xv Beginning Page + 62 Contents Pages + 5 Tables + 18 Figures + 4 Attachments

Based on Kep. Minister of Health 288/Menkes/SK/III/2003 concerning Guidelines for the Health of Facilities and Buildings. Baitussalam Grand Mosque, Magetan Regency, the floors of the toilets and ablution areas look dirty and there are puddles of water which can cause slips/accidents to visitors/congregants as well as the walls of the mosque. The exterior of the mosque and the mosque tower are cracked, the paint color has faded and dirty. This means that at the Baitussalam Grand Mosque, Magetan Regency, some of the mosque buildings/facilities are lacking maintenance/well maintained.

Descriptive research uses 3 variables, namely external buildings, internal buildings and sanitation facilities. This research aims to assess the Sanitary Condition of the Baitussalam Grand Mosque, Magetan Regency by collecting data to assess the Sanitary Condition of the Mosque, namely tools and materials using a questionnaire and stationery. Observations were carried out to determine the Sanitary Condition of the Mosque using a questionnaire. Interviews were conducted to obtain information and research materials using a questionnaire. , Documentation using a documentation camera, Physical measurements using a hygrometer, namely humidity, a thermometer, namely ventilation/temperature, a pH meter, namely physical water.

The results of the research, the condition of the outer building in the Baitussalam Grand Mosque, Magetan Regency is 76 points. Fulfills the requirements, the inner building in the Baitussalam Grand Mosque, Magetan Regency is 462 points. Fulfills the requirements, Sanitation Facilities at the Baitussalam Mosque, Magetan Regency is 400 points. Fulfills the requirements, Sanitation Conditions in the Mosque is 938 points Qualified and physical measurements were taken of Humidity 60%, Temperature 27°C, Physical water (taste, smell and color).

Password : Mosque Sanitation, Baitussalam Grand Mosque, Magetan Regency.