

## ABSTRAK

Shelly Rahmanike Putri

KONDISI SANITASI KAMAR MANDI DAN TOILET DI PASAR KRIAN  
KECAMATAN KRIAN KABUPATEN SIDOARJO TAHUN 2024

xv + 41 Halaman + 8 Tabel + 7 Lampiran

Permasalahan sanitasi lingkungan di pasar masih banyak ditemukan, salah satunya permasalahan fasilitas kamar mandi dan toilet yang belum baik. Hasil observasi pendahuluan ditemukan belum terpisahnya bilik toilet antara perempuan dan laki-laki, penerangan yang kurang, serta ditemukan area penjualan bahan pangan dan makanan matang berdekatan dengan kamar mandi dan toilet. Penelitian ini bertujuan untuk menilai kondisi sanitasi kamar mandi dan toilet di Pasar Krian Kabupaten Sidoarjo.

Penelitian ini termasuk jenis penelitian deskriptif. Variabel yang diperiksa yakni kelengkapan fasilitas, persyaratan bangunan, dan kesesuaian dengan persyaratan kesehatan lingkungan. Subjek penelitian ini yakni 42 bilik kamar mandi dan toilet. Teknik pengumpulan data dilakukan dengan metode observasi dan wawancara. Data yang didapat disusun dalam bentuk tabel kemudian dianalisa secara deskriptif.

Hasil penelitian menunjukkan kondisi sanitasi 42 bilik kamar mandi dan toilet 76,2% cukup dan 23,8% kurang, kelengkapan fasilitas 57,1% cukup, 28,7% kurang, dan 14,2% baik, persyaratan bangunan 50% cukup dan 50% baik, persyaratan kesehatan lingkungan 64,2% cukup, 24,6% kurang, dan 14,2% baik.

Kesimpulan penelitian menunjukkan bahwa kondisi sanitasi kamar mandi dan toilet di Pasar Krian termasuk kategori cukup. Pengelola kamar mandi dan pasar dihimbau untuk memperhatikan dan mengontrol kondisi sanitasi kamar mandi dan toilet pada pasar secara berkala.

Kata Kunci : Sanitasi, Toilet, Pasar Krian

Daftar Pustaka : 3 Buku + 25 Jurnal + 4 Peraturan

## ABSTRACT

Shelly Rahmanike Putri

SANITATION CONDITIONS OF BATHROOM AND TOILET IN KRIAN MARKET KRIAN DISTRICT SIDOARJO CITY YEAR 2024

xv + 41 Pages + 8 Tables + 7 Appendices

There are still many environmental sanitation problems in the market, one of which is the problem of poor bathroom and toilet facilities. Preliminary observation results found toilets that there were no separatetoilet cubicles for women and men, lack of lighting, and found grocery and cooked food sales areas adjacent to bathrooms and toilets. This study aims to assess the sanitary condition of bathrooms and toilets in Krian Market, Sidoarjo Regency.

This study included descriptive research. The variables examined were the completeness of facilities, building requirements, and compliance with environmental health requirements. The subjects of this study were 42 bathroom and toilet cubicles. Data collection techniques were carried out using observation and interview methods. The data obtained were compiled in tabular form and then analyzed descriptively.

The results showed that the sanitary condition of 42 bathroom and toilet cubicles was 76.2% sufficient and 23.8% deficient, the completeness of facilities was 57.1% sufficient, 28.7% deficient, and 14.2% good, building requirements were 50% sufficient and 50% good, environmental health requirements were 64.2% sufficient, 24.6% deficient, and 14.2% good.

The research conclusion shows that the sanitary conditions of bathrooms and toilets in Krian Market is categorized as adequate. Bathroom and market managers are encouraged to pay attention and control the sanitary conditions of bathrooms and toilets in the market regularly.

*Keywords* : Sanitation, Toilets, Krian Market

*Reading List* : 3 Books + 25 Journals + 4 Regulations